


Gen III Transmission "Turn In"



The FMTV's hydraulic Gen III transmission, NSN 2520-01-493-6059, is no longer available in the Army's supply system. The transmission is ARIL coded "C" and needs to be turned in when it becomes an unserviceable asset.

Any of these transmissions that get cast aside in the motor pool rather than turned in puts a stress on the Army's supply system. Without turn-ins, transmissions aren't on hand for repair. That means transmissions are not ready for issue and your vehicle stays NMC!

SO, PACKAGE ANY UNSERVICEABLE TRANSMISSIONS AND RETURN THEM FOR REPAIR AT THE NATIONAL MAINTENANCE LEVEL AT FT BRAGG.

IT'S THE *BEST* WAY TO MAKE SURE THERE'S A REPLACEMENT TRANSMISSION WHEN YOU NEED ONE.

CONTACT YOUR LOCAL TACOM LAR IF YOU NEED HELP.

